

REPUBLIC OF MOLDOVA

PHONE: + 373 22 52 54 75
FAX : + 373 22 52 59 07
AFTN : LUKKYNYX
E-mail : nof@moldatsa.md

AERONAUTICAL INFORMATION SERVICE
MOLDAVIAN AIR TRAFFIC SERVICES AUTHORITY
BD. DACIA 80/4, MD - 2026, CHISINAU

**NOTAM
SUMMARY
07 FEB 2012**

**CHECKLIST OF NOTAM IN FORCE
THE FOLLOWING NOTAM WERE STILL IN FORCE ON 07 FEB 2012,
NOTAM NOT INCLUDED HAVE EITHER BEEN CANCELLED OR SUPERSEDED BY AIP SUPPLEMENT
OR INCORPORATED IN THE AIP MOLDOVA**

SERIES A:	A0389/11 A0417/11 A0442/11 A0443/11 A0007/12 A0008/12 A0009/12 A0010/12 A0012/12 A0013/12 A0014/12 A0015/12 A0016/12 A0017/12 A0018/12 A0019/12 A0020/12 A0021/12 A0022/12 A0024/12 A0026/12
LATEST PUBLICATIONS:	
AIP AMDT	01/2008 DATED 01/05/2008
AIRAC AIP AMDT	03/2008 DATED 22/05/2008 EFFECTIVE 03/07/2008
AIP SUP	012/2008 DATED 03/07/2008
AIC	A03/2008 DATED 01/01/2008
VALID PUBLICATIONS:	
AIP SUP	01/02
AIC	A04/99 A05/99 A06/99 A07/99 A11/99 A01/00 A02/00 A04/00 A01/01 A02/01 A04/01 A03/02 A04/02 A05/02 A06/02 A12/02 A13/02 A01/03 A04/04 A03/05 A04/06 A05/06 A06/06 A01/07 A02/07 A03/07

SUMMARY OF NOTAM IN FORCE

LUUU - CHISINAU - FIR

A0417/11 A)LUUU B)1201010000 C)PERM
E)ALL FLIGHTS PERFORMED FROM 01 JAN 2012 IN THE AIRSPACE OF THE CHISINAU FIR ARE SUBJECT TO EUROCONTROL CONDITIONS OF APPLICATION OF THE ROUTE CHARGES SYSTEM AND CONDITIONS OF PAYMENT.
AMDT AIP MOLDOVA GEN 4.2 SECTION IS MODIFIED AS FOLLOWS:
PARA 1.2.1 - THE VALUE OF THE ROUTE AIR NAVIGATION CHARGES INCLUDING THE ADMINISTRATIVE UNIT RATE ESTABLISHED FOR MOLDOVA AMOUNTS TO EUR 41.09 (EXCLUDING VAT) FROM 01 JANUARY 2012 PER SERVICE UNIT.
PARA 1.2.3 - THE RATE OF INTEREST ON LATE PAYMENT OF ROUTE CHARGES IS 11.57 PER CENT PER ANNUM WITH EFFECT FROM 01 JANUARY 2012.
PARA 2.1.3 - THE RATE OF INTEREST ON LATE PAYMENT OF TANC APPLICABLE FROM 01 JANUARY 2012 IS 11.57 PER CENT PER ANNUM.

A0012/12 A)LUUU B)1203080000 C)1203220000
E)TRIGGER NOTAM - PERM AIRAC AIP AMDT 01/2012 EFF DATE 08/03/2012. GEN 1.7 DIFFERENCES FROM ICAO STANDARDS, RECOMMENDED PRACTICES AND PROCEDURES.
ANNEX 3 - METEOROLOGY - INFORMATION CHANGED.
ANNEX 10 - AERONAUTICAL TELECOMMUNICATIONS - INFORMATION DELETED.

A0013/12 A)LUUU B)1203080000 C)1203220000
E)TRIGGER NOTAM - PERM AIRAC AIP AMDT 01/2012 EFF DATE 08/03/2012. ENR 2.1 FIR, TMA, CTR.
CHISINAU ACC 1 ALTERNATE FREQUENCY CHANGED.

- A0014/12 A)LUUU B)1203080000 C)1203220000
E)TRIGGER NOTAM - PERM AIRAC AIP AMDT 01/2012 EFF DATE 08/03/2012.
ENR 3.3 AREA NAVIGATION (RNAV) ROUTES.
L130, L140, L986, M860, N180, P133, P740, T34 CHISINAU ACC 2
ALTERNATE FREQUENCY ADDED.
- A0015/12 A)LUUU B)1203080000 C)1203220000
E)TRIGGER NOTAM - PERM AIRAC AIP AMDT 01/2012 EFF DATE 08/03/2012.
ENR 3.3 AREA NAVIGATION (RNAV) ROUTES.
L981, M861, N181, N600, N743, N978, T500 CHISINAU ACC 2 ALTERNATE
FREQUENCY ADDED.
- A0016/12 A)LUUU B)1203080000 C)1203220000
E)TRIGGER NOTAM - PERM AIRAC AIP AMDT 01/2012 EFF DATE 08/03/2012.
ENR 3.3 AREA NAVIGATION (RNAV) ROUTES.
UL130, UL140, UL981, UL986, UM406, UM860, UM861, UN180, UN181,
UN190, UN600, UN743, UN978, UP740, UT34, UT500, UZ888 CHISINAU ACC
1 ALTERNATE FREQUENCY CHANGED AND CHISINAU ACC 2 FREQUENCY ADDED.
- A0020/12 A)LUUU B)1202010800 C)1202291500
D)FEB 01 0800-1500 FEB 02-09 14-16 21-24 28 29 0600-1500
E)LUR1 'BALTI' IS ACTIVATED,
REAL-TIME ACTIVITY INFORMATION FROM: ACC2 - 128.975MHZ.
F)GND G)FL105
- A0021/12 A)LUUU B)1202010800 C)1202291500
D)FEB 01 0800-1500 FEB 06 08 09 15 22 24 29 0600-1500
E)LUR3 BULBOACA ACTIVATED.
REAL-TIME ACTIVITY INFORMATION FROM: ACC2 - 128.975MHZ OR
APP - 133.300MHZ, EXPECT RADAR VECTORING.
F)GND G)FL105
- A0022/12 A)LUUU B)1202080600 C)1202291500
D)FEB 08 09 14-16 22 28 29 0600-1500
E)LUR4 CAHUL IS ACTIVATED.
REAL-TIME ACTIVITY INFORMATION FROM: ACC2 - 128.975MHZ.
F)GND G)FL105

LUKK - CHISINAU/INTERNATIONAL

- A0389/11 A)LUKK B)1111141120 C)1202132359EST
E)GROUND TAXI OPERATIONS BETWEEN PARKING POSITIONS NO 9 AND 35
FOR ACFT WITH WING SPAN MORE THAN 30M ARE PERMITTED WITH FOLLOW ME
CAR ONLY. REF AIP MOLDOVA AD2 LUKK 2-7 (28/07/2011).
- A0442/11 A)LUKK B)1112261330 C)PERM
E)ON DISTANCE TABLE OF INSTRUMENT APPROACH CHART LOC RWY 26 INSTEAD
OF
'DME KIV' SHOULD BE 'DME ILD'.
REF AIP MOLDOVA AD 2 LUKK 4-2-5 EFF 17/11/2011.
- A0017/12 A)LUKK B)1203080000 C)1203220000
E)TRIGGER NOTAM - PERM AIRAC AIP AMDT 01/2012 EFF DATE 08/03/2012.
LUKK AD 2.24 - CHARTS RELATED TO AN AERODROME.
VISUAL APPROACH AND BIRD CONCENTRATION CHARTS ADDED.
- A0026/12 A)LUKK B)1202061237 C)1202091500EST
E)WORKING POSITIONS CHISINAU TWR AND CHISINAU GROUND TEMPORARILY
MERGED. OPERATING FREQUENCY 121.800MHZ.

LUBL - BALTI/INTERNATIONAL

- A0443/11 A)LUBL B)1112290643 C)1203291700EST
E)ALL LANDING AREA LIGHTING FACILITIES OUT OF SERVICE.
- A0007/12 A)LUBL B)1201200625 C)1204192359EST
E)NDB RWY 15 LOM 'LCT' ON FREQ 790.0KHZ OUT OF SERVICE.
REF AIP MOLDOVA AD 2. LUBL-5

A0008/12 A)LUBL B)1201200628 C)1204192359EST
E)SID RWY 33 TEMPORARY SUSPENDED DUE TO NDB LOM 'LCT' ON FREQ
790.0KHZ
NOT AVAILABLE.
REF AIP MOLDOVA AD 2 LUBL 5-1-7.

A0009/12 A)LUBL B)1201200630 C)1204192359EST
E)STAR RWY 15 TEMPORARY SUSPENDED DUE TO NDB LOM 'LCT' ON
FREQ 790.0KHZ NOT AVAILABLE.
REF AIP MOLDOVA AD 2 LUBL 3-1-3.

A0010/12 A)LUBL B)1201200632 C)1204192359EST
E)INSTRUMENT APPROACH PROCEDURE NDB RWY 15 TEMPORARY SUSPENDED DUE
TO
NDB LOM 'LCT' ON FREQ 790.0KHZ NOT AVAILABLE.
REF AIP MOLDOVA AD 2. LUBL 4-1-1.

A0018/12 A)LUBL B)1203080000 C)1203220000
E)TRIGGER NOTAM - PERM AIRAC AIP AMDT 01/2012 EFF DATE 08/03/2012.
AD 2 LUBL 4-2-3 INSTRUMENT APPROACH CHART - ICAO ILS RWY 33.
ILS FREQ CORRECTED.

A0024/12 A)LUBL B)1202060800 C)1202071500
E)AD CLSD DUE TO DEACTIVATED ELECTRIC POWER.

CHECKLIST

A0019/12 A)LUUU B)1201300813 C)1203010813EST
E) CHECKLIST
YEAR=2011 0389 0417 0442 0443
YEAR=2012 0001 0007 0008 0009 0010 0012 0013 0014 0015 0016 0017 0018

LATEST PUBLICATIONS
AIP AIRAC AMDT IFR 001/2012 EFFECTIVE DATE 08 MAR 12
AIP SUP IFR 002/2011 EFFECTIVE DATE 28 JUL 11
AIC IFR A004/2012 EFFECTIVE DATE 08 MAR 12)

-END-